

GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:						
	OGM	Pete Hess				

Inspection Report

Permit Number:	C0070045		
Inspection Type:	COMPLETE		
Inspection Date:	Monday, October 04, 2010		
Start Date/Time:	10/4/2010 10:05:00 AM		
End Date/Time:	10/4/2010 11:15:00 AM		
Last Inspection:	Saturday, October 30, 2010		

Inspector: Pete Hess,

Weather: Some cumulo nimbus clouds; some rain overnight

InspectionID Report Number: 2516

Reprocessing

Accepted by: jhelfric 10/6/2010

Permitee: **HEADWATERS ENERGY SERVICES**Operator: **HEADWATERS ENERGY SERVICES**

Site: COVOL SITE

Address: 10653 SOUTH RIVER FRONT PARKWAY, SUITE 300, SOUTH JORDAN UT 840

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

30.00	Total Permitted
30.00	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership	Types of Operations		
☐ Federal	Underground		
☐ State	Surface		
☐ County	Loadout		
☐ Fee	Processing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

☐ Other

Mr. Kyle Edwards represented the Permittee during today's inspection.

Inspector's Signature:

Leter Hess

Date

Monday, October 04, 2910

Pete Hess.

Inspector ID Number: 46

Permit Number: C0070045 Inspection Type: COMPLETE

Inspection Date: Monday, October 04, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark			
2.	Signs and Markers	✓			
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		~	
4.e	Hydrologic Balance: Effluent Limitations	✓		~	
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		~		
7.	Coal Mine Waste, Refuse Piles, Impoundments		~		
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage		~		
11.	Contemporaneous Reclamation		~		
12.	Backfilling And Grading		✓		
13.	Revegetation	✓			
14.	Subsidence Control		✓		
15.	Cessation of Operations		V		
16.	a Roads: Construction, Maintenance, Surfacing	~			
16.	Roads: Drainage Controls	~			
17.	Other Transportation Facilities	V			
18.	Support Facilities, Utility Installations	V			
19.	AVS Check	V			
20.	Air Quality Permit	V		~	
21.	Bonding and Insurance	V		✓	
22.	Other				

Permit Number: C0070045 Inspection Type: COMPLETE

Inspection Date: Monday, October 04, 2010

Page 3 of 3

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The East and West ponds both contained a small volume of water. Mr. Edwards performed the 3rd Quarter impoundment inspections for both ponds on September 1, 2010. There were no signs of instability or erosive action at the ditch inlets or on the in-slopes. The open channel spillways were clear and were capable of functioning as designed. Available sediment storage capacity is in excess of 90%.

4.d Hydrologic Balance: Water Monitoring

The County received rain during the evening hours of 10/3/2010. This was not evident during today's inspection.

4.e Hydrologic Balance: Effluent Limitations

Neither the East pond nor the West has ever been close to discharge elevation.

20. Air Quality Permit

The area between the Ridge Road and the Permit Area main gate has been asphalted to reduce fugitive dust emissions.

21. Bonding and Insurance

The Permittee renewed the general liability insurance coverage for the Wellington facility effective October 1, 2010 through October 1, 2011. The insurers affording coverage are the Illinois Union Fire Insurance Company and the Liberty Mutual Fire Insurance Company. Coverage amounts for each occurrence and general aggregate are two million dollars and four million dollars respectively. The amount of reclamation bond held by the Division for this site remains unchanged.